

# Océ Specifications



## Océ 86500 Check Plot Bond

*Specialty materials for monochrome and color CAD inkjet plotting*

**Product Description** A uncoated bond paper designed to work with monochrome inkjet printing equipment.

<b>Physical Properties*</b>	Weight	20 lb
	Caliper	4.0 mil
	Opacity	86% min.
	Whiteness	145 CIE
	Brightness	92%
	pH	Acid free
	Smoothness	150

**Features** Economical, general purpose bond  
Monochrome dye-based printing capability  
Smooth surface for optimum image density  
Plain paper copy original

<b>Available Sizes &amp; Item numbers</b>	<b>Sheets</b>			
	<i>Width (in)</i>	<i>Length (ft)</i>	<i>Item numbers</i>	<i>Quantity per Carton</i>
24" x	36"	8650000024	100 sheets	
30" x	42"	8650000026	100 sheets	
<b>Rolls</b>				
17" x	150 ft.	8650000001	4 rolls	
18" x	150 ft.	8650000002	4 rolls	
22" x	150 ft.	8650000004	4 rolls	
24" x	150 ft.	8650000006	4 rolls	
30" x	150 ft.	8650000008	4 rolls	
34" x	150 ft.	8650000010	4 rolls	
36" x	150 ft.	8650000013	4 rolls	
42" x	150 ft.	8650000049	4 rolls	
24" x	200 ft.	8650000007	1 roll	
30" x	200 ft.	8650000009	1 roll	
36" x	200 ft.	8650000014	1 roll	

**Océ Imaging Supplies**  
Product Info

*Wide Format Printing Supplies*  
*CAD Inkjet*  
Version 3  
1-13-06

more sizes on page 2



# Océ 86500 Check Plot Bond

## Available Sizes & Item Numbers

<b>Rolls</b>	<i>Width (in)</i>	<i>Length (ft)</i>	<i>Item numbers</i>	<i>Quantity per Carton</i>
	24" x	300 ft.	8650000045	1 roll
	30" x	300 ft.	8650000043	1 roll
	34" x	300 ft.	8650000056	1 roll
	36" x	300 ft.	8650000042	1 roll

**Storage Conditions and Shelf Life** Temperature 60-85°F. (16-30°C) Relative Humidity 30-70%.  
Please repack opened rolls when not in use.  
Shelf life = 1 year when stored at proper conditions.

**Environment, Health & Safety** No Material Safety Data Sheet required.  
Waste is suitable for recycling.

**Main Applications** This product is designed for monochrome CAD applications and plain paper copy originals.

**Processing Tips** Outside of roll is side to be printed.  
Sheets - Side opposite the label is side to be printed.  
Print in a dust and dirt free environment (60°- 85°F, 30-70% RH)  
Check and clean cartridge prior to printing.

## Performance on major CAD inkjet printers

<i>Printer Type</i>	<i>86500</i>
Océ 5350 CS5050/CS5070	X*
CalCompTechJet	X*
EnCad NovaJet Pro, Pro E	--
Hewlett-Packard 250C, 650C	X*
Hewlett-Packard 350C	X*
Hewlett-Packard 750C Family	X*
Hewlett-Packard 1050	X♦
Hewlett-Packard 2500/3500	X*
Hewlett-Packard 500/800	X♦
Xerox	X*

Legend: X = Compatible -- = Not Recommended U = Untested = \* Monochrome only applications  
♦ = Monochrome and color line  
\* = Target Values



**Printing for Professionals**

## Océ North America, Inc.

### Océ Imaging Supplies

1800 Bruning Drive West  
Itasca, IL 60143-1093  
To locate the name of your  
nearest Authorized Océ Media Dealer  
call: 1-888-503-2235  
<http://www.oceusa.com/resourcecenter>  
email: [info@oceusa.com](mailto:info@oceusa.com)

### Océ-Canada, Inc.

4711 Yonge Street, Suite 1100  
Toronto, Ontario, M2N 6K8  
Canada  
1-800-668-1945  
Fax 1-416-224-5600  
email: [INFO@oce.ca](mailto:INFO@oce.ca)